











PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug SL6</p> <p>Manufacturer: Shenzhen Guangda Cable Technology Development Co.,Ltd.</p> <p>Illegal use of FI mark</p>					<p>The product has never been certified by SGS Fimko</p>




FI- mark certificate FI 27844 cancelled 06.03.2014	FI- mark certificate FI 27843, FI 27841 cancelled 02.01.2014
-------------------------------------------------------------	-----------------------------------------------------------------------




PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug 3513 with cord H07RN-F</p> <p>Plug Manufacturer: Decoriental Manufacturing Co., Ltd.</p> <p>Cord manufacturer: Dong Guan Recheer Electric Wire & Cable Co., Ltd.</p> <p>The cable did not pass the bending test at low temperature. This defect may endanger the safety.</p>					<p>NCS FI certificate 26030 is valid until 29.06.2015.</p> <p>The models has been re-tested and approved.</p>




PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Incandescent hand luminaire 474, Plug 4310000 with pink cord</p> <p>Manufacturer: Reimax Electroplast Oy</p> <p>Illegal use of FI mark on luminaire and cord</p>	  				<p>The Incandescent hand luminaire 474 has never been certified by SGS Fimko.</p> <p>Certificate for the plug 25558 A1 is valid until 30.06.2015 but not with pink cable.</p>

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
Type: Overvoltage protector 201-2 and adapter extension cord 1.3M VSKB, H05RN-F, 5x1.5S, 2440365 (1323865) Manufacturer: Reimax Electroplast Oy Illegal use of FI mark					

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plugs 851 and 901 with cord 05RN-F</p> <p>Manufacturer: Reimax Electroplast Oy</p> <p>Cord manufacturer: PECSO</p> <p>Plugs have never been certified with this cord.</p>					<p>Plugs have valid certificates FI 28088 until 07.06.2018 and FI 27813 until 27.12.2017.</p> <p>Plugs have never been certified with cord 05RN-F.</p>


PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug S03 with cord H05RN-F</p> <p>Manufacturer: Ningbo Ousheng Electric Co., Ltd.</p> <p>Cord manufacturer: Ningbo Huashun Electronics Co., Ltd.</p> <p>The cable did not pass the bending test at low temperature. This defect may endanger the safety.</p>					<p>The type has FI 27202 certificate valid until 28.12.2016</p> <p>The cable was improved after this test in 2014.</p>




PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Types: Plugs HL-53 and HL-5B with cord H05VV-F</p> <p>Manufacturer: Zhongshan Guzhen Hongli Cable & Appliance Factory Co., Ltd.</p> <p>Illegal use of FI mark</p>					<p>The products have never been certified by SGS Fimko</p>



PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Types: Plug YS-01 with cord H07RN-F, Plug YS-2 with cord H05RN-F, Plug YS-2 with cord H05RR-F, Plug YS-2 with cord H07RN-F</p> <p>Manufacturer: Shanghai Yusheng Enterprise Development Co., Ltd.</p> <p>The cable did not pass the bending test at low temperature. This defect may endanger the safety.</p>					<p>The plugs have valid certificates FI 26591 until 17.01.2016 and FI 26666 until 18.02.2016.</p> <p>The models listed in production information part are put on hold and using of FI mark is forbidden until cable quality will be improved.</p>





PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Types: Plugs 1610, 1630, 1664, 1668, 1669</p> <p>Manufacturer: Prysmian Cables et Systemes France</p> <p>Illegal use of FI mark</p>					<p>The certificates FI 22232 A2, FI 24210, FI 24212, FI 24213 and FI 24214 were valid until 31.12.2009.</p>


PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Power supply unit, switch mode PS14K0502000E5</p> <p>Manufacturer: Unknown</p> <p>(Misuse of Flypower product) Illegal use of SGS GS mark</p>	 <p>The image shows a black rectangular power adapter. The label on the adapter reads: 'FLYPOWER Switching adapter', 'MODEL:PS14K0502000E5', 'INPUT:100-240V~', '50/60Hz 0.35A', 'OUTPUT:5.0V--- 2000mA'. It also features several certification marks including CE, a V in a circle, a crossed-out trash can, and the SGS GS mark. At the bottom, it says 'Made in China'.</p>				<p>The manufacturer Flypower has valid SGS GS certificate until 03.04.2018 for real their product.</p>

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug ZH-1 with cord H05RN-F</p> <p>Manufacturer: Wuxi Zhonghui Wire & Cable Co., Ltd.</p> <p>The cable did not pass the bending test at low temperature. This defect may endanger the safety.</p>				<p>The plug has valid certificate FI 28648 until 10.07.2019.</p> <p>The model listed in production information part is put on hold and using of FI mark is forbidden until cable quality will be improved.</p>	

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug SY-22</p> <p>Manufacturer: Sheng Yi Electrical Factory</p> <p>Illegal use of FI mark</p>					<p>The product has never been certified by SGS Fimko</p>



PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug HQ-B301</p> <p>Manufacturer: Guangzhou Huanqiu Electrical & Appliance Co., Ltd.</p> <p>Illegal use of FI mark</p>					<p>The validity of certificate FI 23655 was ended on 31.12.2009.</p>


PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug GH-003</p> <p>Manufacturer: Ningbo Huashun Electronics Co., Ltd.</p> <p>Illegal use of FI mark</p>					<p>The validity of certificate FI 24867 was ended on 31.12.2009.</p>

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Plug RF-01</p> <p>Manufacturer: Guangdong Rifeng Electrical Cable Co., Ltd.</p> <p>Illegal use of FI mark</p>					<p>The certificate FI 27656 was cancelled on 11.12.2013.</p>

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
Type: Luminaire AWR 12, Photoelectrically controlled switch PXA 54 Manufacturer: Ensto Finland Oy Illegal use of FI mark					The product has never been certified by SGS Fimko
Type: Tween light, Arona, 56392-4D, Star fan, Mini tower fan 35W, TF-103846 Manufacturer: Bahag AG Illegal use of FI mark					The products have never been FI certified by SGS Fimko The products has valid SGS GS certificate GS/13/HEL/00303 until 26.03.2018. For the second model validity of GS/13/HEL/00489 has ended on 21.11.2014

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
Type: Electric Heater, oil fitted 400W, 1383.100 Manufacturer: Gnösjö Konstmide Ab Illegal use of FI mark					The product has never been certified by SGS Fimko
Type: Cord H05VV-F 3G1 Manufacturer: Ta An Electric Co., Ltd. Illegal use of FI mark					The certificate FI 24405 has ended on 02.07.2013.

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Connector A-150 and Plug YX-207</p> <p>Manufacturer: FORTLAND Industrial Co.</p> <p>Illegal use of FI mark</p>					<p>The product has never been certified by SGS Fimko</p>

PRODUCT INFORMATION	PICTURE	PICTURE	PICTURE	PICTURE	OTHER INFORMATION
<p>Type: Installation box RIT-50</p> <p>Manufacturer: HT Hi Tech Polymers Oy</p> <p>Illegal use of FI mark</p>					<p>The product has never been certified by SGS Fimko</p>