








UNAUTHORIZED OR ILLEGAL USE OF SGS CERTIFICATION MARKS  
IN 2012

11.9.2012

PRODUCT INFORMATION	PICTURE		PICTURE		CERTIFICATION MARK
<p>Cable reel type 27347 Importer Kauppahuone Harju Oy Manufacturer Unknown Product has never been certified by SGS Fimko</p>					<p>FI</p>
<p>Connector Type IS-19 with cord H05RR-F and other cords H05RN-F and H07RN-F Manufactured by I-Sheng Electric &lt;wire &amp; Cable <b>The cable did not pass the bending test at low temperature</b> <b>This defect endangers the safety</b></p>					<p>FI</p>
<p>Kaoyi Electronic Step-down converter KTB-150 Has never been certified by SGS Fimko</p>					<p>FI</p>

UNAUTHORIZED OR ILLEGAL USE OF SGS CERTIFICATION MARKS  
IN 2012

11.9.2012

PRODUCT INFORMATION	PICTURE		PICTURE		CERTIFICATION MARK
<p>Shenzhen Dongju Plug, non-rewirable DJ-012 with cord H05VV-F Has no valid SGS Fimko's FI certificate.</p>					
<p>Plug, non-rewirable BL02, manufactured by Shining Blick Enterprices Co., Ltd Cables H05RN-F, H07RN-F and H05RNH2-F. Manufactured by Dong Guan Yong Tai Electric Wire &amp; Cable The cables did not pass the bending test at low temperature. This defect endangers he safety (H05RN-F and H07RN-F) and may endanger the safety (H05RNH2-F)</p>					FI
<p>Ta Hsing Connector, non-rewirable TA-5H manufactured by Ta Hsing Electric Wire &amp; Cable Co.,Ltd The rubber cables did not pass the impact test at low temperature This defect may endanger the safety</p>					FI

UNAUTHORIZED OR ILLEGAL USE OF SGS CERTIFICATION MARKS  
IN 2012

11.9.2012

PRODUCT INFORMATION	PICTURE			
<p>Type: Rubber cable H05RN-F            Manufacturer: Don Guan Recheer            Electric Wire &amp; Cable Co.,Ltd            The cable did not pass the bending            test at low temperature            This defect may endanger the            safety</p>	